

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/11/2023

Submitted Date:

01/11/2023

Document Number:

696304645

**FIELD INSPECTION FORM**Loc ID 428695 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
| ,            |       | Inspections@civiresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 428692      | WELL | PR     | 09/01/2022  | OW         | 123-35472 | Esterling 44-33H | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | TANK LABELS/PLACARDS  |       |            |
| Comment:             | North Produced Water Tank is missing Labels - NFPA, Content and Capacity; see photos<br>Drain Pit at Compressor is missing Capacity Label |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.h.   | Date: | 02/10/2023 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                               |                             |       |                 |
|-------------------------------|-----------------------------|-------|-----------------|
| <b>Equipment:</b>             |                             |       | corrective date |
| Type: Compressor              | # 1                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Flare                   | # 1                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Ancillary equipment     | # 1                         |       |                 |
| Comment:                      | Generator                   |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Pump Jack               | # 1                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Emission Control Device | # 1                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Gas Meter Run           | # 2                         |       |                 |
| Comment:                      |                             |       |                 |
| Corrective Action:            |                             | Date: |                 |
| Type: Ancillary equipment     | # 1                         |       |                 |
| Comment:                      | Propane Tank - 1000 Gallons |       |                 |

|                                   |                                  |       |  |
|-----------------------------------|----------------------------------|-------|--|
| Corrective Action:                |                                  | Date: |  |
| Type: Bradenhead                  | # 1                              |       |  |
| Comment:                          | Appears to be plumbed to surface |       |  |
| Corrective Action:                |                                  | Date: |  |
| Type: Horizontal Heated Separator | # 1                              |       |  |
| Comment:                          |                                  |       |  |
| Corrective Action:                |                                  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 2 | 500 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type             | Tank ID | SE GPS                |
|--------------------|---|----------|------------------|---------|-----------------------|
| CRUDE OIL          | 4 | 500 BBLS | HEATED STEEL AST |         | 40.437740,-104.206280 |
| Comment:           |   |          |                  |         |                       |
| Corrective Action: |   |          |                  |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|          |    |  |
|----------|----|--|
| Yes/No   | NO |  |
| Comment: |    |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                             |                                     |                       |            |                  |
|-----------------------------|-------------------------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                                     |                       |            |                  |
| Facility ID: 428692         | Type: WELL                          | API Number: 123-35472 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                                     |                       |            |                  |
| Comment:                    | PR - Returned to Production 09/2022 |                       |            |                  |
| Corrective Action:          |                                     |                       |            | Date:            |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <a href="#">Routine Field Inspection. Tank Labels</a> | petrie | 01/11/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403287286    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5979204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5979204</a> |
| 696304646    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5979199">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5979199</a> |