

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2023

Submitted Date:

01/17/2023

Document Number:

699805409

FIELD INSPECTION FORM
 Loc ID 334736 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291185	WELL	PR	02/29/2008	GW	045-14320	CHEROKEE MOUNTAIN ESTATES 3-14C (N3E)	PR
291187	WELL	PR	02/06/2008	GW	045-14319	CHEROKEE MOUNTAIN ESTATES 3-14D (N3E)	PR
291191	WELL	PR	03/19/2008	GW	045-14318	CHEROKEE MOUNTAIN ESTATES 3-14B (N3E)	PR
292499	WELL	PR	01/31/2008	GW	045-14746	CHEROKEE MOUNTAIN ESTATES 3-15 (N3E)	PR
292501	WELL	PR	02/09/2008	GW	045-14747	CHEROKEE MOUNTIAN ESTATES 10-3 (N3E)	PR
293735	WELL	PR	01/29/2008	GW	045-15124	CHEROKEE MOUNTAIN ESTATES 3-15A (N3E)	PR

General Comment:**COGCC Inspection Report Summary**

On 1/17/23 at approximately 11:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC CHEROKEE MOUNTAIN ESTATES-67S92W /3SESW.

Location #334857 Garfield County Colorado

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Chemical tank label weathered and not legible with a corrective action date of 2/17/23.

- Location is located in a high priority habitat area

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of the report.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank label weathered and not legible.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	02/17/2023
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Vertical Heated Separator	# 5				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Chemical tank refer to Signs/Markers for corrective actions			
Corrective Action:				Date:	
Type: Bradenhead	# 5				
Comment:		Pressure transducers located on braden head. All braden head valves are accessible.			
Corrective Action:				Date:	
Type: Gas Meter Run	# 5				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 5				
Comment:		All wells on plunger lift			
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:		Summit midstream			
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Centralized containment			
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:					

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Centralized containment					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291185	Type:	WELL	API Number:	045-14320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291187	Type:	WELL	API Number:	045-14319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291191	Type:	WELL	API Number:	045-14318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292499	Type:	WELL	API Number:	045-14746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292501	Type:	WELL	API Number:	045-14747	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293735	Type:	WELL	API Number:	045-15124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
		Check Dams				
Sediment Traps						
		Sediment Traps				
		Ditches				
		Berms				
Compaction						
Berms						
Ditches						

Comment: Limited storm water inspection due to location being covered with snow. Location appears to have been plowed within the confines of the BMP's of location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers for corrective actions.	depaoloc	01/17/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805410	Photos for Insp. #699805409	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5989415