

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2023

Submitted Date:

01/23/2023

Document Number:

679605349

FIELD INSPECTION FORMLoc ID 457767 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10671

Name of Operator: EDGE ENERGY II LLC

Address: 600 12TH STREET SUITE 115

City: GOLDEN State: CO Zip: 80401

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Turner, Ben		bturner@edgeenergy1.com	Engineering; All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457766	WELL	PR	08/01/2020	OW	123-48072	Simpson 36-1H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds near compressor. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	01/30/2023
Type	UNUSED EQUIPMENT		
Comment:	Unsed equipment near compressor. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	07/22/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	anchored		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	400 BBLs	STEEL AST		,	
Comment:	anchored					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST		,	
Comment:	anchored					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					

Inspected Facilities				
Facility ID: 457766	Type: WELL	API Number: 123-48072	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679604803. 2 out of 3 corrective actions previously assigned to this location have been resolved. The unresolved previous corrective action has been re-assigned to this location with its original corrective action date. One new corrective action was also observed at the time of re-inspection. Please view narrative below for more details.</p> <p>COGCC Inspection Report Summary **Weather Conditions: cloudy, approx. 5" of snow On Monday, January 23, 2023 at approximately 11:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at SIMPSON 36-1H (Edge Energy II LLC), at location #: 457767 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. Weeds on location near compressor. Remove to comply with Rule 606. (Corrective Action Date: January 30, 2023) See attached photos #7. 2. Unused equipment near compressor. Remove or reconnect equipment to comply with Rule 606. (Corrective Action Date: July 22, 2022) See attached photos #7-9. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	01/23/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679605350	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5993686