

# Inspection Photos

01/23/2023

Operator: VISION ENERGY LLC #10770

Location #312658

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 1:** Photo taken from the Location entrance facing south. Photos example showing BMPs to stabilize the Location, and to minimize tracking and sediment transport remains missing or insufficient.



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 2:** Photos example showing BMPs to stabilize the Location, and to minimize tracking and sediment transport remains missing or insufficient.



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 3:** Photos taken from the south end of the Location facing west and north. Photos example showing BMPs to stabilize the Location, and to minimize tracking and sediment transport remains missing or insufficient.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



January 23, 2023



January 23, 2023

**Photo 4:** Photos taken from the east end of the Location. Photos examples showing stormwater and erosion control BMPs to stabilize the Location, and to manage runoff remain missing or insufficient; erosion degradation has persisted.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 5:** See comment under photo 4.

Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 6:** Photo taken from the west end of the Location. Photo shows stormwater runoff from the location has not been managed in a manner that minimizes erosion and degradation; gully erosion evident on offsite areas west of Location





January 23, 2023

**Photo 7:** Photo shows Operator has attempted to install required signage at the wellhead per Rule 605.d, however, the labeling (marker) has degraded and is once again illegible.



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 8:** Photo taken from the tank battery. Vegetation remains evident within the secondary containment; secondary containment is not in proper functioning condition, or adequate in size to contain a spill from the tank. Vegetation within BMP compromises the impermeability of the containment.



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 9:** See comments under photo 8.



Inspection Photos  
Operator Name: VISION ENERGY LLC #10770  
Location #312658



**Photo 10:** Photo example showing anchors missing required marking.

