

Inspection Photos

January 26, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 425899

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Inspection Document #: 702801189

Garfield County, CO

SWNW Section 23 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 1. Photo taken from the west shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 2. Photos show degradation to the pad surface and a lack of stabilization BMPs and tracking controls.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 3. Photo taken at the east of the location shows an overview of the eroding cut slope behind the separators.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 4. Photos taken at the east of the location show the cut slope behind the separators. The erosion blanket is degraded, sediment has overtopped wattles, stabilizing perennial plants appear sparse. Sediment is accumulating at the base of the slope.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 5. Photo shows BMP degradation and cut slope erosion. Soils were observed to be actively falling from the slope from gravity (not wind or water) indicating a particularly unstable slope. See also attached video.

Inspection Photos
Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692
Location ID: 425899



Photo 6. Photos taken to the south of the separators, where the working pad meets the access road shows a large gully.



Inspection Photos
Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692
Location ID: 425899



Photo 7. Photos taken from the southern edge of the location shows where stormwater is undermining/cutting beneath rip-rap, armoring the fill slope (left, red arrow). A wattle installed below has been overtopped (blue arrow, right).



Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 8. Photos show staining at wellheads.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos
Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692
Location ID: 425899



Photo 9. Photos show production areas.



Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 10. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189

Inspection Photos

Location Name: Dixon Federal Pad (SWNW-23-692)/11A-23-692

Location ID: 425899



Photo 11. Photo shows the interim area/fill slope at the southwest of the location. The slope appears sparsely vegetated with perennial grasses.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801189