

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403309160

Date Received:
02/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800931

Inspection Date: 11/08/2022

FIR Submit Date: 11/14/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335613

Location Name: FEDERAL-66S94W Number: 11NWNW County: _____

Qtrqr: NWN Sec: 11 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.545044 Longitude: -107.861588

FACILITY - API Number: 05-045- -00 Facility ID: 335613

Facility Name: FEDERAL-66S94W Number: 11NWNW

Qtrqr: NWN Sec: 11 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.545044 Longitude: -107.861588

CORRECTIVE ACTIONS:

2 CA# 166113

Corrective Action: Install proper guy line markers per Rule 1003.a or remove anchors if equipment unnecessary.

Date: 11/28/2022

Response: CA COMPLETED

Date of Completion: 11/17/2022

Operator
Comment:

Anchors were marked on 11/17/22. Corrective action complete.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 166184

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/09/2022

Response: CA COMPLETED

Date of Completion: 11/08/2022

Operator Comment: Pumper was dispatched to location and used vac-truck to evacuate all storm water from the well cellar immediately. The pumper discovered that a casing master valve had developed a small leak. The pumper re-packed the casing master valve with grease and successfully stopped the leak. Corrective action complete.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 2/1/2023 12:40:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files