

Construction and Stormwater Inspection

Date: 01/24/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 457136

Inspection Document #: 696105695

Weld County, CO

NWSE Section 14 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



1/24/23, 10:37 AM
207° SW

Photo 1. Facing southwest at at production equipment. Photo illustrates tumbleweed accumulations within production equipment.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 2. Facing west at production equipment; see comments in Photo 1.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



1/24/23, 10:38 AM
316° NW

Photo 3. Facing northwest at production equipment; see comments in Photo 1.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 4. Facing south at production equipment; see comments in Photo 1.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 5. Facing south near the southern portion of the location. Partially buried debris observed on location.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 6. Facing northeast near wellheads. Photo illustrates flatbed trailer being stored on location; this is considered unused equipment and needs to be removed.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 7. Facing north near the wellhead. Oil stained soil was observed near the wellhead that needs to be properly cleaned up and removed.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 8. Facing north near the wellheads. Debris (e.g. wood) observed on location and needs to be removed.



Photos 9 & 10. Close up photo near Well API #123-47788 illustrating an unmarked opening/excavation near the wellhead. Staff was able to stick a 4.5' shovel into the opening without touching the bottom and did not observe any signs/fence/covers to indicate an open excavation was present.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photos 11 & 12. Facing north near the center/northeastern portion of the location. Photos illustrate accumulation of tumbleweeds within equipment that are now considered debris and need to be removed. Additionally, the tanks do not have adequate labels as no NFPA placards or content labels were observed (with the exception of one content label on the left side in photo 11). Unknown material was also observed around the tank opening (Photo 12) that needs to be properly cleaned up.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photos 13 & 14. Facing northeast and north from the northeast corner of the location. Debris was observed partially buried in snow and will need to be removed.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 15. Facing south near the locations entrance; see comments in Photos 13 & 14.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 16. Facing north from the location's entrance. Photo illustrates pipeline construction beginning; crews were on site clearing snow and staging materials and equipment during this inspection.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 17. Facing south near county road entrance to the location; see comments in Photo 16.

Inspection Photos
Location Name: Rohn 9-60 14A
Location ID: 457136



Photo 18. Facing west; see comments in Photo 16.