

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2023

Submitted Date:

01/30/2023

Document Number:

694500554**FIELD INSPECTION FORM**Loc ID 436007 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 952 ECHO LANE SUITE 480City: HOUSTON State: TX Zip: 77024**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Justin Blohm		justin.blohm@fulcrumeo.com	
Penner, Annalee		Annalee.Penner@fulcrumeo.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483729	SPILL OR RELEASE	AC	01/25/2023		-	Valve to storage tank	EI

**General Comment:**

Spill was reported to COGCC by Fulcrum staff. COGCC inspected spill 483729 on 1/26/23. Weather was 8 deg, windy and overcast. The following was observed; it appeared that spilled fluid was contained inside secondary containment, water that was spilled was frozen inside the Lined secondary containment (dirt Berm). Valve that was froze was replaced. Fulcrum Field staff, Wes, was present and discussed the response with COGCC. Crews were planning on removing ice (produced water) and restore the secondary containment volume. At the time of inspection crews were removing the ice by chipping and shoveling, Wes mentioned that they may use hot water and vac trucks. Corrective action: file 10-day supplemental Form 19, Handle all spilled fluid and Ice as E&P waste. see attached Photos. well was pumping at time of inspection.

Inspected Facilities									
Facility ID:	483729	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)	
Comment					
Corrective Action				Date:	

**Spill/Remediation:**

Comment:	All spilled and/or removed material shall be handled as E&P waste.		
Corrective Action:	Dispose of E&P waste per COGCC rules.	Date:	02/13/2023

Emission Control Burner (ECB): NO

Comment: Pilot:  Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403306668	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003377</a>
694500555	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003370</a>