

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2023

Submitted Date:

01/30/2023

Document Number:

695107396

FIELD INSPECTION FORM

Loc ID 334225 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258602	WELL	PR	12/01/2020	CBM	071-07108	MUSTANG 41-30	PR
288570	WELL	PR	04/06/2007	CBM	071-09121	MUSTANG 41-30 TR	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment: **PHOTO 5: UNUSED EQUIPMENT STORED NEAR ORIG WELLHEAD (TBG & RODS).**

Corrective Action: **REMOVE UNUSED EQUIPMENT PER RULE 606.**

Date: 02/10/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Ancillary equipment

2

Comment:

Corrective Action:

Date:

Type: Progressive Cavity

2

Comment: **ORIGINAL DRIVEHEAD IS ELECTRIC DRIVE**

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

6

Comment:

Corrective Action:

Date:

Type: Vertical Separator

2

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

2

Comment: **BOTH ARE ACCESSABLE**

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 261861 Lat: 37.235222 Long: -104.813236

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC#695105652, CA'S HAVE BEEN ADDRESSED HOWEVER THERE IS A NEW CA, SEE HOUSEKEEPING SECTION FOR DETAILS.	beardslt	01/30/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403306682	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003433
695107397	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6003409