

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2023

Submitted Date:

02/06/2023

Document Number:

696204615

FIELD INSPECTION FORMLoc ID 334733 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334733	LOCATION	AC			-	MAP LLC-67S95W 11NESW	RI

General Comment:

On 2/3/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's MAP LLC-67S95W 11NESW location in Garfield County, Colorado.

This inspection is a follow-up to #696204467 to document compliance with the following corrective actions:

-Maintain liner at tank battery.

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

New compliance issues per this inspection:

-Storage of unused equipment

Refer to the "Location" and "stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused pipe equipment observed improperly stored on the south end of the Location.		
Corrective Action:	Comply with Rule 606.	Date:	02/21/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal		Walls Insufficient		Inadequate	
Comment:	<p>Inspection #696204467 observed that the Liner at the tank battery facility was in disrepair; several holes/tears/etc... observed throughout the entire liner; Secondary containment is not sufficiently impervious to contain spilled or released materials. Inspection required Operator to install or repair BMP to ensure containment remains impervious to contain spilled or released materials by 1/9/2023</p> <p>Holes/tears remain apparent at the liner. This corrective action has not been addressed and remains applicable.</p>				
Corrective Action:	Install or repair BMP to ensure containment remains impervious to contain spilled or released materials.			Date:	01/09/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	334733	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Limited visibility stormwater inspection due to winter conditions and snow cover; no immediate stormwater issues observed at time of inspection.						Date: _____
Corrective Action: 						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403312719	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6010309
696204617	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6010305