

Interim Reclamation and Stormwater Inspection

Date: 02/10/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 454591

Inspection Document #: 696105736

Weld County, CO

NENE Section 14 T8N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 1 & 2. Facing northwest from the topsoil stockpile. Photos illustrate evidence of bare soil and undesirable vegetation (e.g. kochia and russian thistle).

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 3 & 4. Facing north and northwest towards interim areas. Evidence of bare soil within the interim area.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 5 & 6. Facing northeast and southwest at open excavation. Crews were on site and reminded to put fence up when left unattended.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 7 & 8. Tumbleweed accumulations were observed throughout the location and within equipment. This is now considered debris and needs to be removed.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 9 & 10. See comments in Photos 7 & 8.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 11 & 12. See comments in Photos 7 & 8.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 13 & 14. See comments in Photos 7 & 8.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 15 & 16. Wildlife netting around secondary containment is not adequate and will need to be repaired or replaced.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 17 & 18. Unknown red fluid observed on skid of compressor, located on the northeastern portion of the location.

Inspection Photos

Location Name: Boomslang Fed 8-60 14A

Location ID: 454591



Photos 19 & 20. Crude oil was observed near production equipment on the eastern portion of the location, north of tank battery; this will need to be properly cleaned up per 912.a.