

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2023

Submitted Date:

02/07/2023

Document Number:

707800166

**FIELD INSPECTION FORM**Loc ID 335001 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291094	WELL	PR	11/10/2008	GW	045-14303	CIRCLE B LAND 11A-35-692	PR
291095	WELL	PR	10/01/2022	GW	045-14302	CIRCLE B LAND 11D-35-692	PR
291097	WELL	PR	11/12/2008	GW	045-14301	CIRCLE B LAND 12C-35-692	PR
291099	WELL	PR	11/05/2008	GW	045-14300	CIRCLE B LAND 12B-35-629	PR
294937	WELL	PR	11/14/2008	GW	045-15639	CIRCLE B LAND 13D-35-692	PR
294938	WELL	PR	11/04/2008	GW	045-15638	CIRCLE B LAND 11B-35-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 2/6/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Circle B1, at Location # 335001 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Some C/A's from previous inspections document # 700703380 have not been completed.

During this inspection the following compliance issues were observed:

1. Stored/unused equipment remains from previous inspection.
2. Holes in tank secondary containment.
3. Two different emergency contact number on tank at well heads.
4. Well head signage is faded and some is illegible.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well head signage is faded and some are illegible.		
Corrective Action:	Replace or repair signage	Date:	03/10/2023
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Two different emergency contact number on tank at well heads.		
Corrective Action:	Provide proper labeling on tank	Date:	03/10/2023

**Emergency Contact Number:**

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Stored/unused equipment remains from previous inspection.		
Corrective Action:	Remove unused equipment	Date:	03/10/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	See unused equipment		
Corrective Action:		Date:	

Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	Shared containment with 500 BBL condensate tanks. See Condensate tanks for C/A			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal		Walls Insufficient			
Comment: Holes in tank secondary containment.					
Corrective Action: Provide sufficient containment to contain possible spill				Date:	03/10/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291094	Type:	WELL	API Number:	045-14303	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291095	Type:	WELL	API Number:	045-14302	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291097	Type:	WELL	API Number:	045-14301	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291099	Type:	WELL	API Number:	045-14300	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294937	Type:	WELL	API Number:	045-15639	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	294938	Type:	WELL	API Number:	045-15638	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Berms						

Comment: Corrective Action: Date: Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403316176	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014204</a>
707800170	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014197</a>