

Interim Reclamation and Stormwater Inspection

Date: 02/14/2023

Operator: RED HAWK PETROLEUM LLC - 430811

Location ID: 430811

Inspection Document #: 696105744

Weld County, CO

SWSE Section 19 T7N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 1 & 2. Facing west towards the interim reclamation areas. During this inspection some desirable vegetation was observed as well as undesirable vegetation (e.g. kochia and russian thistle). The operator will have to manage this location for undesirable vegetation during this next growing season. A follow-up inspection will be conducted at a later date to ensure compliance with Rule 1003 standards.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 3. Facing south near the location's entrance; see comments in Photos 1 & 2.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 4. Facing west from the southern portion of the location; see comments in Photos 1 & 2.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photo 5. Facing west from the southern portion of the location; see comments in Photos 1 & 2.



Photo 6. Facing southwest from the southern portion of the location. Photo illustrates tumbleweed accumulations along fence line that are now considered debris and need to be removed.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 7 & 8. Close-up photos of tank battery. Photos illustrate oily waste that will need to be properly cleaned up per Rule 905.e.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 9 & 10. Close up photos of stained soil and debris. Left photo illustrates oily waste that will need to be cleaned up and right photo shows debris observed within the containment area of the tank battery.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 11 & 12. Close up photos of debris (e.g. glass, metal, tumbleweeds) observed near the pump jack.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 13 & 14. Facing northwest and southeast along the western portion of the location. Photos illustrate undesirable vegetation throughout the location that will need to be managed in the next growing season.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811



Photos 15 & 16. Facing northeast and southwest from the western earthen berm BMP. Photos illustrate presence of undesirable vegetation and gully erosion, or a breach, in the perimeter BMP. This will need to be repaired to prevent sediment laden stormwater from exiting off location.

Inspection Photos
Location Name: Logan 2H
Location ID: 430811




Photo 17. Close-up photo of gully erosion, boot for scale. See comments in Photos 15 & 16.