


**TEP Rocky Mountain LLC**  
**Specialty Restaurants SG 13-33**  
**Location #383331**



**Entrance to location**



**Tank battery sign**

TEP Rocky Mountain LLC  
Specialty Restaurants SG 13-33  
Location #383331




Line leak



Line leak



**TEP Rocky Mountain LLC  
Specialty Restaurants SG 13-33  
Location #383331**



**Debris around wellhead**



**Uncapped loadline on produced water tank**

**TEP Rocky Mountain LLC  
Specialty Restaurants SG 13-33  
Location #383331**



**Open valve on loadline**



**Open end tank valve**



**TEP Rocky Mountain LLC  
Specialty Restaurants SG 13-33  
Location #383331**



**Lack of stabilization**



**Lack of stabilization**



**TEP Rocky Mountain LLC  
Specialty Restaurants SG 13-33  
Location #383331**



**Lack of stabilization**



**Lack of stabilization**