

Caerus Piceance LLC
Nolte 14-796
Location #435806



Sign at entrance to location



From entrance to location

Caerus Piceance LLC
Nolte 14-796
Location #435806



From entrance to location



From entrance to location

Caerus Piceance LLC
Nolte 14-796
Location #435806



Debris around wellheads



Debris around wellheads

Caerus Piceance LLC
Nolte 14-796
Location #435806



Debris inside tank battery



Debris inside tank battery

Caerus Piceance LLC
Nolte 14-796
Location #435806




Label torn and illegible



Label torn and illegible



Caerus Piceance LLC
Nolte 14-796
Location #435806



Missing tank label



Uncapped loadline on produced water tank

Caerus Piceance LLC
Nolte 14-796
Location #435806



Open end loadline on condensate tank



Lack of stabilization

Caerus Piceance LLC
Nolte 14-796
Location #435806



Lack of stabilization



Lack of stabilization