

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Entrance to location

From well pad

TEP Rocky Mountain LLC Mobil GM 24-27 Pad Location #335397



From well pad



Exposed mouseholes

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Southern exposed mousehole

Northern exposed mousehole

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Random debris around several wellheads



Random debris around wellheads including piping

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Open end loadlines on condensate and produced water tanks



Debris inside tank battery containment

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Random debris on chemical tank containments



Chemical containment full of liquid

**TEP Rocky Mountain LLC
Mobil GM 24-27 Pad
Location #335397**



Feb 9, 2023 at 8:57:20 AM



Feb 9, 2023 at 9:02:14 AM

Lack of stabilization

Lack of stabilization