

# Interim Reclamation and Stormwater Inspection

Date: 02/14/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 432352

Inspection Document #: 696105746

Weld County, CO

SWSW Section 16 T7N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 1.** Facing northeast near the location's entrance. Photo illustrates that undesirable vegetation was observed throughout the interim reclamation areas. The operator will need to manage the location for undesirable vegetation during the next growing season to ensure compliance with Rule 1003.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 2.** Facing west from the western portion of the location; see comments in Photo 1.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 3.** Facing northwest, from the western portion of location; see comments in Photo 1.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 4.** Facing east from the northern portion of location; see comments in Photo 1.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 5.** Facing west from the northern portion; russian thistle and kochia observed.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 6.** Facing south from the northeast corner of location; see comments in Photo 1.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 7.** Facing east at pump jack; tumbleweed accumulations within equipment are considered debris and need to be removed as they are a potential fire hazard.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 8.** Facing southwest; see comments in Photo 7.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 9.** Facing southeast from the northwest corner of production area; see comments in Photo 7.



Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



**Photo 10.** Facing south at tank battery; see comments in Photo 7.

Inspection Photos  
Location Name: State 16-7-60 1H  
Location ID: 432352



2/14/23, 11:18 AM  
222° SW  
COGCC

**Photo 11.** Facing southwest at tank battery; See comments in Photo 7.