

# Interim Reclamation and Stormwater Inspection

Date: 02/15/2023

Operator: VERDAD RESOURCES LLC- 10651

Location ID: 424238

Inspection Document #: 696105748

Weld County, CO

SESE Section 3 T7N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 1.** Facing south from the center of location; Debris was observed on location (e.g. tire and pipe) that will need to be removed.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 2.** Facing south from the western interim reclamation area. Due to snow cover, Staff was unable to verify vegetation and the location will need to be inspected at a future date to ensure compliance with Rule 1003 standards.

Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 3.** Facing north; see comments in Photo 2.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 4.** Facing northeast at the former/reclaimed pit; see comments in Photo 2.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 5.** Facing south from on top of the topsoil stockpile. Photo illustrates some desirable vegetation (e.g. buffalo grass) was observed during this inspection and the location will be inspected at a future date to verify vegetation standards in accordance to Rule 1003.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 6.** Facing east at combustor; tumbleweed accumulations were observed near and around equipment and are considered debris. The operator will need to remove this potential fire hazard.

Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 7.** Facing south at treater/gauge station; see comments in Photo 6.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 8.** Facing north at the tank battery; see comments in Photo 6.



Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 9.** Facing northwest at the pump jack; see comments in Photo 6.




Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 10.** Facing southwest at the wellhead; see comments in Photo 6.

Inspection Photos  
Location Name: Pergamos 3-44-7-60  
Location ID: 424238



**Photo 11.** Facing north at the wellhead. Oil stained soil was observed during this inspection. The operator shall clean up the stained soil and perform maintenance on equipment to ensure leaks are addressed.