

# Interim Reclamation and Stormwater Inspection

Date: 02/14/2023

Operator: RED HAWK PETROLEUM - 10503

Location ID: 438327

Inspection Document #: 696105751

Weld County, CO

SESW Section 2 T7N R60W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 1.** Facing south from the access road to the location. It appears the road has drifted in and been plowed. Any material inadvertently removed from the access road shall be placed back to its relative position once snow has melted to prevent off-site degradation to adjacent lands. No CA is being issued at this time.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 2.** Facing north from the interim areas. Due to snow cover, this location will be inspected at a future date to ensure compliance with Rule 1003 standards.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 3.** Facing east from the topsoil stockpile on the northern portion of the location; see comments in Photo 2.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 4.** Facing southwest from topsoil stockpile area; see comments in Photo 2.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photos 5 & 6.** Facing south and north at the wellheads/pump jacks. Photos illustrate tumbleweed accumulations within equipment that needs to be removed as it is a potential fire hazard. Additionally, oil stained soil was observed near the wellheads that will need to be properly disposed of.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



Photos 7 & 8. See comments in Photos 5 & 6.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327




**Photo 9.** See comments in Photos 5 & 6.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photos 10 & 11.** Facing southeast at combustor and northwest at treaters. See comments in Photos 5 & 6.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 12.** Facing northwest at wellhead. Oil stained soil was observed along with free fluid on equipment.



**Photo 13.** Facing southwest at one of the pump jacks. Wildlife netting is not adequate and/or properly installed.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photos 14 & 15.** Facing northwest and east at the tank battery. Photos illustrates oil stained soil (left) and oily waste (right) that needs to be properly disposed of.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photos 16 & 17.** Facing north at the tank battery (south side). Debris (e.g. broken glass) was observed under ladder and will now need to be cleaned up as it's considered debris.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 18.** Debris observed within containment area of tank battery that will need to be removed.

Inspection Photos  
Location Name: Loomis 2-1H  
Location ID: 438327



**Photo 19.** Facing northeast near combustor. Road maintainer being stored on location and will need to be removed. As a reminder, locations are not to be used as storage or lay-down yards.