

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9003 From entrance to location.



Photo #9004 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9005 From entrance to location.



Photo #9006 Methanol tank information inaccurate.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9007 Unused supplies.



Photo #9015 Multiple places with debris on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9016 Multiple places with debris on location.



Photo # 9008 Slope stabilization BMP's insufficient.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9009 Slope stabilization BMP's insufficient.



Photo #9010 Run on to location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY-66S92W /17SESW

Location ID: 335547



Photo #9009 Slope stabilization BMP's insufficient.