

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2023

Submitted Date:

02/17/2023

Document Number:

707800189

FIELD INSPECTION FORM

Loc ID: 324684 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 14 Number of Comments
 7 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, COGCC		shaun.kellerby@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
, COGCC		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212427	WELL	PR	03/01/2022	OW	057-06320	FEDERAL 5-27X	PR
480891	TANK BATTERY	AC	10/07/2021		-	South McCallum Tank Battery	AC

General Comment:

COGCC Inspection Report Summary
 On Thursday 2/16/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at KPK South McCallum tank battery, at Location # 480891 in Jackson county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.
 C/A's from previous inspection (Propane torch inside secondary tank containment and tank thief hatch open) document # 707800185 have been completed. Propane torch was removed and thief hatch was closed. All other C/A's are still in place.
 During this inspection the following possible compliance issues were observed:

1. Random debris
2. Multiple staining at tanks and well head.
3. Lack of battery signage.
4. Open holes for wildlife to enter.
5. Line on tank not capped or plugged.
6. Diesel tank labeling is illegible
7. Diesel tank is lacking secondary containment.

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Provide proper signage	Date:	03/29/2023
Type	CONTAINERS		
Comment:	Diesel tank labeling is illegible		
Corrective Action:	Provide proper labeling	Date:	03/03/2023
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-825-4822/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open holes for wildlife to enter		
Corrective Action:	Eliminate possibility of wildlife to enter open lines	Date:	02/24/2023
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove all debris	Date:	02/24/2023
Type	OTHER		
Comment:	Line on tank not capped or plugged.		
Corrective Action:	Install cap or plug	Date:	02/24/2023
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove all stained and impacted material and dispose of properly	Date:	02/24/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	# 1		corrective date
---------------------------	-----	--	-----------------

Comment:	Portable generator.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	500 gallon diesel Not in a containment		Date:	
Corrective Action:	Provide proper secondary containment		Date:	03/03/2023
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		
Comment:	One tank is heated.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	16,000 gallons
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		Date:
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 212427 Type: WELL API Number: 057-06320 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 480891 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800190	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6026080