


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HERRERA-66S92W /20NESE

Location ID: 335445



**Photo #9017 From entrance to location.**



**Photo #9018 From entrance to location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HERRERA-66S92W /20NESE

Location ID: 335445



Photo #9019 From entrance to location.



Photo #9020 Multiple tank labels weathered and not legible.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HERRERA-66S92W /20NESE

Location ID: 335445



Photo #9021 Multiple tank labels weathered and not legible.



Photo #9022 unused equipment.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HERRERA-66S92W /20NESE

Location ID: 335445



Photo #9023 Unused equipment.



Photo #9024 Unused equipment.