

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2023

Submitted Date:

02/17/2023

Document Number:

699805445

FIELD INSPECTION FORM

Loc ID 335119	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 22 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277335	WELL	PR	11/24/2005	GW	045-10678	ANCHONDO 42B-20-692	PR
277336	WELL	PR	11/04/2005	GW	045-10679	ANCHONDO 42D-20-692	PR
277337	WELL	PR	12/29/2005	GW	045-10680	ANCHONDO 32D-20-692	PR
277338	WELL	PR	10/28/2005	GW	045-10681	ANCHONDO 32B-20-692	PR
290416	WELL	PR	05/03/2012	GW	045-14104	ANCHONDO 32A-20-692	PR
290417	WELL	PR	04/17/2012	GW	045-14103	ANCHONDO 32C-20-692	PR
290418	WELL	PR	10/09/2007	GW	045-14102	ANCHONDO 42A-20-692	PR
290419	WELL	PR	10/03/2007	GW	045-14101	ANCHONDO 42C-20-692	PR

General Comment:

COGCC Inspection Report Summary
 On 2/14/23 at approximately 14:30 hours, I, Inspector Corey De Paolo,
 Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC ANCHONDO-66S92W /20SENE.
 Location #335119 Garfield County Colorado
 Refer to inspection #700704249 conducted on 5/24/22. Previous corrective actions have not been completed.
 While there, I observed normal production operations.
 During this inspection the following compliance issues were observed:

1) Unused equipment with a previous corrective action date of 7/7/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of the inspection report

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank. Batteries not in secondary containment		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused equipment.		
Corrective Action:	The storage of equipment and supplies not necessary for use on location is prohibited.	Date:	07/07/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:	Livestock panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Refer to Housekeeping for corrective actions		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		Centralized containment						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
PRODUCED WATER	2	300 BBLs	STEEL AST		,			
Comment:								
Corrective Action:							Date:	
<u>Paint</u>								
Condition	Adequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate				
Comment:		Centralized containment						
Corrective Action:							Date:	
<u>Venting:</u>								
Yes/No	NO							
Comment:								
Corrective Action:						Date:		
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:						Date:		

Inspected Facilities									
Facility ID:	277335	Type:	WELL	API Number:	045-10678	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277336	Type:	WELL	API Number:	045-10679	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277337	Type:	WELL	API Number:	045-10680	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	277338	Type:	WELL	API Number:	045-10681	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	290416	Type:	WELL	API Number:	045-14104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	290417	Type:	WELL	API Number:	045-14103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	290418	Type:	WELL	API Number:	045-14102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	290419	Type:	WELL	API Number:	045-14101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Ditches						
Berms						
		Compaction				
Gravel						
		Gravel				
		Ditches				
		Berms				
		Culverts				
Sediment Traps						

Comment: Limited storm water inspection due to location being covered with snow. Location appears to have been plowed within the confines of the BMP's of location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Housekeeping for corrective actions.	depaoloc	02/17/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805446	Photos for Insp. #699805445	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6026349