

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2023

Submitted Date:

02/27/2023

Document Number:

707800201**FIELD INSPECTION FORM**Loc ID 334962 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267006	WELL	PR	12/01/2022	GW	045-09192	MILLER 5-36	PR
267007	WELL	PR	10/01/2010	GW	045-09191	MILLER 4-36	PR
412889	WELL	PR	06/09/2010	GW	045-18680	MILLER 23D-36-692	PR
412890	WELL	PR	06/09/2010	GW	045-18681	MILLER 22A-36-692	PR
412891	WELL	PR	06/15/2010	GW	045-18682	MILLER 23C-36-692	PR
412892	WELL	PR	06/09/2010	GW	045-18683	MILLER 13D-36-692	PR
412893	WELL	PR	06/17/2010	GW	045-18684	MILLER 13C-36-692	PR
412894	WELL	PR	05/27/2010	GW	045-18685	MILLER 12D-36-692	PR
412895	WELL	PR	05/12/2010	GW	045-18686	MILLER 12C-36-692	PR
412896	WELL	PR	05/27/2010	GW	045-18687	MILLER 11A-36-692	PR
412897	WELL	PR	05/27/2010	GW	045-18688	MILLER 11B-36-692	PR
412898	WELL	PR	05/12/2010	GW	045-18689	MILLER 11D-36-692	PR
412899	WELL	PR	06/17/2010	GW	045-18690	MILLER 12A-36-692	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 2/23/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Miller 4-36, at Location # 334962 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Inspection is conducted also for complaint on CB4 SWD. I witnessed in the time frame of inspections around CB4 SWD 3 bob tail trucks and 1 transport truck in the 4 hours of inspections at locations in close proximity to CB4 SWD.

C/A (storm water) from previous inspection document # 700702281 could not be assessed due to heavy snow cover.

During this inspection the following compliance issues were observed:

1. Stored/unused equipment (ECD disconnected)

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:Comment: [TEP 911/970-285-9377](tel:TEP 911/970-285-9377)

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL			
Comment:	Stored/unused equipment (ECD disconnected)			
Corrective Action:	Remove unused/stored equipment		Date:	03/27/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 13		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Two Chemical tanks in plastic containments, One 500 gallon methanol tank in metal containment.		
Corrective Action:		Date:	

Type: Plunger Lift	# 13		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 13		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	See stored/unused equipment for C/A		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	OTHER	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	625 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	267006	Type:	WELL	API Number:	045-09192	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	267007	Type:	WELL	API Number:	045-09191	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412889	Type:	WELL	API Number:	045-18680	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412890	Type:	WELL	API Number:	045-18681	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412891	Type:	WELL	API Number:	045-18682	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412892	Type:	WELL	API Number:	045-18683	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412893	Type:	WELL	API Number:	045-18684	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	412894	Type:	WELL	API Number:	045-18685	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	412895	Type:	WELL	API Number:	045-18686	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	412896	Type:	WELL	API Number:	045-18687	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	412897	Type:	WELL	API Number:	045-18688	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	412898	Type:	WELL	API Number:	045-18689	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	412899	Type:	WELL	API Number:	045-18690	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Culverts				
Berms						
Retention Ponds						
		Ditches				

Comment: [C/A \(storm water\) from previous inspection document # 700702281 could not be assessed due to heavy snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800205	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6035980