

Inspection Photos

2/27/2023

Operator: CAERUS PICEANCE LLC - 10456

Location #423081

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



February 27, 2023



February 27, 2023

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



February 27, 2023



February 27, 2023

Photo 3: Photo of tank battery facility. Sign not posted or information pursuant to Rule 605.e. is missing or inaccurate at the tank battery.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



February 27, 2023



February 27, 2023

Photo 4: Photo example showing holes observed within secondary containment liner at the tank battery facility. Patch previously applied to hole has peeled off.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



Photo 5: Methanol tanks- containment BMPs partially filled with fluids. Advise removal of fluids to ensure containment BMP remains in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



February 27, 2023



February 27, 2023

Photo 6: Photos 6-8 provide overview of the Interim areas of the Location. Limited reclamation inspection due to winter conditions; areas appear to be progressing towards 1003 standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



February 27, 2023



February 27, 2023

Photo 7: See comments under photo 6.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



Photo 8: See comments under photo 6.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location #423081



Photo 9: Photo taken from the access road entrance, from the County Road (Stone Quarry Rd). Photos show BMPs to minimize tracking and sediment transport are missing or insufficient; tracking/sediment transport from the access road onto the County Road observed.