

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2023

Submitted Date:

02/24/2023

Document Number:

699805457

FIELD INSPECTION FORMLoc ID 422328 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

23 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422297	WELL	PR	08/07/2012	GW	045-20544	Cook Exxon 17-16C (PB-20)	PR
422298	WELL	PR	08/01/2020	GW	045-20545	Cook Gardner 20-4A (PB-20)	PR
422299	WELL	PR	09/13/2012	GW	045-20546	Cook Exxon 20-5BB (PB-20)	PR
422307	WELL	PR	08/01/2020	GW	045-20551	Cook Martin 20-1C (PB-20)	PR
422311	WELL	PR	09/13/2012	GW	045-20554	Cook Gardner 20-4BB (PB-20)	PR
422315	WELL	PR	09/13/2012	GW	045-20557	Cook Carpenter 20-3C (PB-20)	PR
422316	WELL	PR	08/01/2020	GW	045-20558	Cook Carpenter 20-3A (PB-20)	PR
422318	WELL	PR	09/13/2012	GW	045-20559	Cook Martin 20-1D (PB-20)	PR
422321	WELL	PR	09/13/2012	GW	045-20561	Cook Gardner 20-4 (PB-20)	PR

General Comment:

COGCC Inspection Report Summary

On 2/23/23 at approximately 12:-00 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC Cook Martin /20-1D (PB-20).

Location #422328 Garfield County Colorado

This inspection is response to complaint #403314212.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Chemical tank missing required information with a corrective action date of 3/23/23.
- 2) Flow line heating insulation open ended and not capped with a corrective action date of 3/3/23.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of the inspection report

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Chemical tank missing required information.			
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled.			Date: 03/23/2023
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-2615			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire fence around location			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 2			corrective date

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flow line heating insulation open ended and not capped.		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date:	03/03/2023
Type: Bradenhead	# 9		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:	Combustor appeared to be on at the time of inspection.	
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	422297	Type:	WELL	API Number:	045-20544	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422298	Type:	WELL	API Number:	045-20545	Status:	PR	Insp. Status:	PR
Complaint									
Comment:	This inspection is in response to complaint #402811614.								
Corrective Action:						Date:			
Facility ID:	422299	Type:	WELL	API Number:	045-20546	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422307	Type:	WELL	API Number:	045-20551	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422311	Type:	WELL	API Number:	045-20554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422315	Type:	WELL	API Number:	045-20557	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422316	Type:	WELL	API Number:	045-20558	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422318	Type:	WELL	API Number:	045-20559	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	422321	Type:	WELL	API Number:	045-20561	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						
		Ditches				
		Berms				
		Culverts				
		Compaction				
Ditches						

Comment: [Limited storm water inspection due to location being covered with snow. Location appears to have been plowed within the confines of the BMP's of location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers and Equipment for corrective actions.	depaoloc	02/24/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403330442	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6032859
699805458	Photos for Insp. #699805457	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6032855