

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2023

Submitted Date:

03/08/2023

Document Number:

696204738

**FIELD INSPECTION FORM**Loc ID 324199 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264430	WELL	PR	03/01/2019	GW	045-08212	CHEVRON 42-8	RI
324199	LOCATION	AC			-	CHEVRON-66S96W 8SENE	RI

**General Comment:**

On 3/06/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's CHEVRON-66S96W/8SENE Location in Garfield County, Colorado.

This inspection is a follow-up to #696204596 to document compliance with the following corrective actions:  
-Inadequate Secondary Containment

It was observed in this inspection that the corrective action has not been addressed.

The following new compliance issues were observed per this inspection:  
-Stormwater

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location****Lease Road:**

Type			
comment:	See "Stormwater"		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	1-866-580-9382/911		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal pipe		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel/barbed wire combination		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,

Comment:	<p>Inspection #696204596 observed that secondary containment is not sufficiently impervious to contain spilled or released materials; various holes/tears observed throughout liner.</p> <p>Inspection required Operator to maintain BMP to ensure containment is sufficiently impervious to contain spill or release.</p> <p>It was observed in this inspection that the corrective action has not been addressed; holes/tears remain throughout liner.</p>	
Corrective Action:	Maintain BMP to ensure containment is sufficiently impervious to contain spill or release.	Date: 02/25/2023

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>264430</u>	Type:	<u>WELL</u>	API Number:	<u>045-08212</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>324199</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments".](#)

Corrective Action: [Comply with Rule 1002.f: Install or repair required BMPs, including tracking BMPs on the Location and access road.](#)

Date: 03/11/2023

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">STORWMATER COMMENT</a></p> <p>BMPs to minimize erosion, degradation, tracking and sediment transport are missing or insufficient at Location and access road:</p> <p>-Piles of soil observed placed along the eastern perimeter of the Location; soils unconsolidated; sediment transport BMPs missing; soils observed covering vegetation.</p> <p>-BMPs to stabilize, as well as to manage runoff, minimize erosion, degradation, tracking and sediment transport missing or insufficient on the working pad area, and the main North/South access road Leading to the Location; tracking/rutting apparent; degradation and sediment transport observed.</p>	trujilloam	03/08/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204739	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044558">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044558</a>