

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2023

Submitted Date:

03/08/2023

Document Number:

696204740

**FIELD INSPECTION FORM**Loc ID 335795 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC.inspections@caerus oilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275459	WELL	PR	03/01/2019	GW	045-13546	CHEVRON 42A-8D	RI
275466	WELL	SI	11/01/2022	GW	045-13547	CHEVRON 41D-8D	RI
335795	LOCATION	AC			-	CHEVRON-66S96W 8NENE	RI

**General Comment:**

On 3/06/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's CHEVRON-66S96W/8NENE Location in Garfield County, Colorado.

This inspection is a follow-up to #696204598 to document compliance with the following corrective actions:  
-Inadequate Secondary Containment

It was observed in this inspection that the corrective action has not been addressed.

The following new compliance issues were observed per this inspection:  
-Stormwater

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type			
comment:	See "Stormwater"		
Corrective ActionL		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-866-580-9382/911

Corrective Action:

Date:

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal Pipe		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Paneling/Barbed wire combination		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						

Corrective Action:		Date:		
<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient	Base Insufficient	Inadequate
Comment:	<p>Inspection #696204598 observed that secondary containment is not sufficiently impervious to contain spilled or released materials; various holes/tears observed throughout liner. Inspection required Operator to maintain BMP to ensure containment is sufficiently impervious to contain spill or release.</p> <p>It was observed in this inspection that BMP has not been maintained; holes/tears remain throughout liner.</p>			
Corrective Action:	Maintain BMP to ensure containment is sufficiently impervious to contain spill or release.			Date: 02/26/2023
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	<u>275459</u>	Type:	<u>WELL</u>	API Number:	<u>045-13546</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>275466</u>	Type:	<u>WELL</u>	API Number:	<u>045-13547</u>	Status:	<u>SI</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>335795</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: <span style="color: blue;">BMPs to stabilize, as well as to minimize erosion, degradation, tracking and sediment transport are missing or insufficient at the North/South access road Leading to the Location; tracking/rutting apparent; BMPs to manage stormwater runoff missing or insufficient; sediment transport observed.</span></p> <p>Corrective Action: <span style="color: red;">Comply with Rule 1002.f: Install or repair required BMPs on the Location and access road.</span> Date: 03/11/2023</p> <p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204741	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044559">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044559</a>