

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2023

Submitted Date:

03/08/2023

Document Number:

708900087

FIELD INSPECTION FORMLoc ID 334596 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Depaolo, Corey		corey.depaulo@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259464	WELL	PR	03/06/2001	GW	045-07732	AMERICAN SODA GM 266-3	PR
282174	WELL	PR	03/18/2006	GW	045-11696	SOLVAY CHEMICALS GM 541-3	PR
282176	WELL	PR	03/18/2006	GW	045-11695	SOLVAY CHEMICALS GM 441-3	PR

General Comment:**COGCC Inspection Report Summary**

On 03/07/2023 at approximately 12:10 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 266-3 pad.

Location # 334596 in Garfield County Colorado.

Location is located in a high priority habitat area.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Materials Handling/Spill Prevention with a CA date of 03/15/2023
2. Open ended load line with a CA date of 03/15/2023
3. Signs/Marker - Wellhead sign missing with a CA date of 04/07/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	GM 266-3 well missing sign		
Corrective Action:	A permanent sign will be conspicuously located at the wellhead	Date:	04/07/2023
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Taylor plugs located on all 3 bradenhead, all bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	All load lines will be capped or plugged	Date:	03/15/2023
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:	All 8 deadman marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	259464	Type:	WELL	API Number:	045-07732	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, on plunger lift								
Corrective Action:						Date:			
Facility ID:	282174	Type:	WELL	API Number:	045-11696	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, on plunger lift								
Corrective Action:						Date:			
Facility ID:	282176	Type:	WELL	API Number:	045-11695	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
Berms						
Gravel						Sparse
Compaction						Light
		Compaction				Light
				Material Handling And Spill Prevention	Fail	Battery improperly stored
Ditches						

Comment: [Battery improperly stored](#)Corrective Action: [Operators shall implement BMPs in accordance with good engineering practices, including measures such as: Materials handling and spill prevention procedures and practices implemented for material handling and spill prevention of materials used, stored, or disposed of that could result in discharges causing pollution of surface waters.](#)Date: 03/15/2023Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker, Equipment & Stormwater for observed compliance issues.	smelserw	03/08/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900088	Inspection 708900087 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044751