

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2023

Submitted Date:

03/08/2023

Document Number:

696204738

FIELD INSPECTION FORM

 Loc ID 324199 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264430	WELL	PR	03/01/2019	GW	045-08212	CHEVRON 42-8	RI
324199	LOCATION	AC			-	CHEVRON-66S96W 8SENE	RI

General Comment:

On 3/06/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's CHEVRON-66S96W/8SENE Location in Garfield County, Colorado.

This inspection is a follow-up to #696204596 to document compliance with the following corrective actions:
 -Inadequate Secondary Containment

It was observed in this inspection that the corrective action has not been addressed.

The following new compliance issues were observed per this inspection:
 -Stormwater

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type			
comment:	See "Stormwater"		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	1-866-580-9382/911		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal pipe		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel/barbed wire combination		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,

Comment:	<p>Inspection #696204596 observed that secondary containment is not sufficiently impervious to contain spilled or released materials; various holes/tears observed throughout liner.</p> <p>Inspection required Operator to maintain BMP to ensure containment is sufficiently impervious to contain spill or release.</p> <p>It was observed in this inspection that the corrective action has not been addressed; holes/tears remain throughout liner.</p>	
Corrective Action:	Maintain BMP to ensure containment is sufficiently impervious to contain spill or release.	Date: 02/25/2023

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 264430 Type: WELL API Number: 045-08212 Status: PR Insp. Status: RI

Facility ID: 324199 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments".](#)

Corrective Action: **Comply with Rule 1002.f: Install or repair required BMPs, including tracking BMPs on the Location and access road.**

Date: 03/11/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>STORWMATER COMMENT</p> <p>BMPs to minimize erosion, degradation, tracking and sediment transport are missing or insufficient at Location and access road:</p> <p>-Piles of soil observed placed along the eastern perimeter of the Location; soils unconsolidated; sediment transport BMPs missing; soils observed covering vegetation.</p> <p>-BMPs to stabilize, as well as to manage runoff, minimize erosion, degradation, tracking and sediment transport missing or insufficient on the working pad area, and the main North/South access road Leading to the Location; tracking/rutting apparent; degradation and sediment transport observed.</p>	trujilloam	03/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403341071	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044580
696204739	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044558