

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2023

Submitted Date:

03/08/2023

Document Number:

696204742

FIELD INSPECTION FORM
 Loc ID 335781 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270378	WELL	PR	03/01/2019	GW	045-09541	CHEVRON 21A-17D	RI
270380	WELL	SI	07/01/2022	GW	045-09542	CHEVRON 22A-17D	RI
270382	WELL	PR	03/01/2019	GW	045-09543	CHEVRON 21C-17D	RI
335781	LOCATION	AC			-	Parachute Creek 5A	RI
446089	WELL	PR	09/19/2017	GW	045-23236	Chevron 11C-17	RI
446090	WELL	PR	03/01/2019	GW	045-23237	Chevron 22E-17	RI
446091	WELL	PR	09/23/2017	GW	045-23238	Chevron 21C-17	RI
446092	WELL	PR	09/14/2017	GW	045-23239	Chevron 11D-17	RI
446093	WELL	PR	03/01/2019	GW	045-23240	Chevron 21E-17	RI
446094	WELL	PR	09/07/2017	GW	045-23241	Chevron 21B-17	RI
446095	WELL	PR	09/14/2017	GW	045-23242	Chevron 21D-17	RI
446096	WELL	PR	09/13/2017	GW	045-23243	Chevron 12A-17	RI
446097	WELL	PR	09/10/2017	GW	045-23244	Chevron 22B-17	RI
446098	WELL	PR	09/06/2017	GW	045-23245	Chevron 11A-17	RI

General Comment:

On 3/06/2023, Reclamation Specialist Trujillo inspected Caerus Piceance's Parachute Creek 5A Location in Garfield County, Colorado.

This inspection is a follow-up to #696204600 to document compliance with the following corrective actions:

- Signage missing at battery
- Fence in disrepair
- Stormwater; working pad lacks stabilization

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective actions.

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Inspection #696204600 observed signage missing at the tank battery. Inspection required Operator to comply with Rule 605.a. It was observed in this inspection that signage has been installed; CA has been addressed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-866-580-9382/911

Corrective Action:

Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels / barbed wire combination		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fence at separator has been repaired.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares containment with four 400 bbl produced water tanks. Liner observed separating from containment; maintenance advised.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares containment with two 400 bbl condensate tanks. Liner observed separating from containment; maintenance advised.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>270378</u>	Type:	<u>WELL</u>	API Number:	<u>045-09541</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>270380</u>	Type:	<u>WELL</u>	API Number:	<u>045-09542</u>	Status:	<u>SI</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>270382</u>	Type:	<u>WELL</u>	API Number:	<u>045-09543</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>335781</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446089</u>	Type:	<u>WELL</u>	API Number:	<u>045-23236</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446090</u>	Type:	<u>WELL</u>	API Number:	<u>045-23237</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446091</u>	Type:	<u>WELL</u>	API Number:	<u>045-23238</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446092</u>	Type:	<u>WELL</u>	API Number:	<u>045-23239</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446093</u>	Type:	<u>WELL</u>	API Number:	<u>045-23240</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446094</u>	Type:	<u>WELL</u>	API Number:	<u>045-23241</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446095</u>	Type:	<u>WELL</u>	API Number:	<u>045-23242</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446096</u>	Type:	<u>WELL</u>	API Number:	<u>045-23243</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446097</u>	Type:	<u>WELL</u>	API Number:	<u>045-23244</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>446098</u>	Type:	<u>WELL</u>	API Number:	<u>045-23245</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696204600 observed that BMPs to stabilize the working pad, and to minimize degradation, tracking and off-site sediment transport are missing or insufficient. Inspection required Operator to comply with Rule 1002.f.

It was observed in this inspection that BMPs remain missing or insufficient; CA has not been addressed and remains applicable.

Corrective Action: **Install or maintain BMPs per good engineering practices, in accordance with Rule 1002.f**

Date: 01/28/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403341078	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044596
696204743	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6044560