

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2023

Submitted Date:

03/09/2023

Document Number:

708900089**FIELD INSPECTION FORM**Loc ID: 324175 Inspector Name: Smelser, Wayne On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Depaolo, Corey		corey.depaulo@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261483	WELL	PR	10/18/2001	GW	045-07961	AMERICAN SODA GM 254-2	PR

General Comment:**COGCC Inspection Report Summary**

On 03/07/2023 at approximately 11:00 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC AMERICAN SODA GM 254-2 pad.

Location # 324175 in Garfield County Colorado.

Location is located in a high priority habitat area.

Location is in close proximity to Parachute Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Vehicle track/No Tracking BMP at entrance to location with a CA date of 03/16/2023
2. Housekeeping - Barbed wire laying on the ground in multiple locations with a CA date of 03/16/2023
3. Equipment - Improperly marked deadman with a CA date of 03/24/2023
4. Equipment - Production unit lacks bird protectors with a CA date of 03/16/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Separator unit include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Bardbed wire laying on the ground in multiple areas around location.			
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.			Date: 03/16/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Hog panels			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Hog panels			

Corrective Action:		Date:	
Type	LOCATION		
Comment:	Security fence & barbed wire fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	1 deadman properly marked 1 deadman improperly marked		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	03/24/2023
Type: Bird Protectors	# 2		
Comment:	Bird protectors missing on separator burners		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources	Date:	03/16/2023
Type: Bradenhead	# 1		
Comment:	Pressure transducer located on bradenhead. Bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent		
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	261483	Type:	WELL	API Number:	045-07961	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail					Gravel Insufficient
		Compaction				
		Ditches				
				Vehicle Tracking	Fail	Insufficient tracking BMP at entrance to location
Compaction	Fail					Lack of stabilization
		Gravel				Sparse gravel

Comment: [Lack of stabilization on location, insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.](#)

Date: 03/16/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping, Equipment & Stormwater for observed compliance issues.	smelserw	03/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403342548	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046066
708900092	Inspection 708900089 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046065