

Interim Reclamation and Stormwater Inspection

Date: 03/15/2023

Operator: BISON IV OPERATING LLC - 10670

Location ID: 455365

Inspection Document #: 708200060

Weld County, CO

NENW Section 29 T8N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 1. Facing east from the location entrance. Temporary BMPs have been installed (ditch and berm) around the entire perimeter during the construction phase of the location. More permanent BMPs should be installed upon the completion of pad expansion.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 2. Facing east from the northern portion of the location; see comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 3. Facing southwest from the northeast corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 4. Facing northwest from the southeast corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 5. Facing northeast from the southwest corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 6. Facing south from the location's entrance; see comments in Photo 1.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 7. Facing northeast towards the new topsoil stockpile. Construction activities were occurring at the time of this inspection; topsoil salvage operations are still ongoing and the material is being segregated on the northeastern portion of the location.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 8. Facing northwest at the topsoil stockpile; see comments in Photo 7.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 9. Facing south from topsoil stockpile; salvage operations were still on-going. Staff observed some evidence of equipment tracking on the stockpile and it is required by Rule 1002.c that the entire topsoil stockpile is temporarily stabilized prior to long term stabilization efforts occur.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 10. Facing north from topsoil; see comments in Photo 9.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 11. Facing west from the southern portion of the location. Topsoil salvage operations were still occurring during this inspection. The Operator shall ensure that all topsoil is properly salvaged and segregated.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 12. Facing west from the southern portion of the location; photo illustrates cut and fill areas during the pad expansion/construction activities.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 13. Facing southwest near one of the new well locations; see comments in Photo 12.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 14. Facing east from southern portion of location; see comments in Photo 12.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 15. Facing northeast from the southwest corner of the location; see comments in Photo 12.

Inspection Photos
Location Name: Shoveler Pad
Location ID: 455365



Photo 16. Taken from southeast corner of the location. Trash and debris accumulations observed on location; all trash and debris will need to be cleaned up and disposed of in compliance with Rule 606.