

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2509 From entrance to location



Photo # 2510 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2511 Location



Photo # 2512 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2513 Location



Photo # 2517 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2518 Meter calibration info not conspicuously posted



Photo # 2519 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2520 Battery sign not maintained/properly posted



Photo # 2522 Gulley erosion along lease road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2523 Culvert needs maintenance (lease road)



Photo # 2524 Culvert needs maintenance (lease road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2530 Gulley erosion on lease road



Photo # 2531 Erosion & sediment migration off lease road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2534 Ditch along lease road needs maintenance



Photo # 2535 Ditch along lease road needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL GM 11-2 Pad

Location ID: 334771



Photo # 2536 Ditch along lease road needs maintenance



Photo # 2527 Ditch along lease road needs maintenance