

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2417 From entrance to location



Photo # 2418 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2419 Location



Photo # 2420 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2421 Location



Photo # 2423 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397




Photo # 2424 Open ended load line



Photo # 2425 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2426 Open ended load line



Photo # 2427 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2430 Open ended load line



Photo # 2428 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2429 Debris



Photo # 2431 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2432 Meter calibration info not conspicuously posted

Photo # 2433 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2434 Gully erosion on spur road into pad



Photo # 2435 Ditch needs maintenance (Towards SW corner of pad 6-10 ft from sediment trap)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2437 Hay bales/BMP needs maintenance (NW corner just off location near separators)



Photo # 2438 Gulley erosion into ditch (NE corner near tank battery)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2439 Check Dam needs maintenance (NE corner of location near tank battery)



Photo # 2440 Sediment Trap needs maintenance (NE corner of location near tank battery)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2441 Sediment Trap needs maintenance (NE corner of location near tank battery)



Photo # 2442 Sediment Trap needs maintenance (East side of location across from wellheads)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WRIGHT, CASTEEL AND SMALLWOOD SG 24-28

Location ID: 334397



Photo # 2447 Rip Rap needs maintenance (on lease road approximately 600 yards past the I-70 underpass)



Photo # 2448 Culverts need maintenance (on lease road approximately 600 yards past the I-70 underpass)