

Inspection Photos
Location Name: Rollie J Vincent A #1
Location ID:332911



Photo 1 Well head



Photo 2 PU

Inspection Photos

Location Name: Rollie J Vincent A #1

Location ID:332911



Photo 3 Well head sign



Photo 4 Stained soil and mechanical issue 1" Flow line



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rollie J Vincent A #1
Location ID:332911



Photo 5 Stained soil under gas powered motor



Photo 6 Gas powered motor muffler appears to be rusted out, rust cracks are visible.

Inspection Photos
Location Name: Rollie J Vincent A #1
Location ID:332911



Photo 7 production equipment: ECD and Hoz separator were in operation at time of inspection. DEBRIS (dead weeds around equipment).



Photo 8 TNK BTRY DEBRIS (dead weeds in and around containment).

Inspection Photos
Location Name: Rollie J Vincent A #1
Location ID:332911



Photo 9 Mete show .1 MCF production



Photo 10 Shows production date of 3-6-23