

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 334-32

Location ID: 413524



Photo # 2571 From entrance to location



Photo # 2572 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 334-32

Location ID: 413524



Photo # 2574 Location



Photo # 2575 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 334-32

Location ID: 413524



Photo # 2576 Location



Photo # 2578 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 334-32

Location ID: 413524



Photo # 2577 Meter calibration info not conspicuously posted



Photo # 2584 Gulley erosion on location, 40 yards SW of solar panels

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 334-32

Location ID: 413524



Photo # 2585 Gulley erosion at entrance to location north side



Photo # 2586 Gulley erosion on lease road 40 yards from tracking pad on the west side