

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2703 From entrance to location



Photo # 2704 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2705 From entrance to location



Photo # 2706 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2707 Location



Photo # 2708 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2709 Location



Photo # 2711 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2712 Meter calibration info not conspicuously posted



Photo # 2715 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2716 Open ended load line



Photo # 2717 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2718 Containment liner needs maintenance



Photo # 2719 Rill erosion/insufficient run on control (BMP)/sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2720 Rill erosion/insufficient run on control (BMP)/sediment encroaching on equipment



Photo # 2722 Rill erosion/insufficient run on control (BMP)/sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2723 Rill erosion/insufficient run on control (BMP)/sediment encroaching on equipment



Photo # 2724 Rill erosion/insufficient run on control (BMP)/sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2726 Channel erosion/insufficient BMP



Photo # 2727 Channel erosion/insufficient BMP

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2731 Sediment choking off vegetation



Photo # 2732 Sediment Trap needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2733 Sediment Trap needs maintenance



Photo # 2736 Hay bales need maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BORUCH GM 24-12 pad

Location ID: 334722



Photo # 2737 Hay bales need maintenance



Photo # 2738 Gulley erosion near entrance to location