

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2673 From entrance to location



Photo # 2675 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2676 Location



Photo # 2677 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2678 Location



Photo # 2679 Meter calibration info not conspicuously posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2680 Open ended load line



Photo # 2682 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2683 Containment needs maintenance



Photo # 2684 Containment needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2686 Containment needs maintenance



Photo # 2688 SG 431-32 wellhead sign missing



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2660 Erosion & Transport of sediment off spur road



Photo # 2662 Sediment trap needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2664 Sediment trap & ditch need maintenance



Photo # 2663 Rill erosion on spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2665 Rill erosion on spur road



Photo # 2667 Rill erosion on spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2668 Culvert needs maintenance



Photo # 2671 Hay bales need maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Mar 20, 2023 at 12:18:34 PM
CO



Mar 20, 2023 at 12:41:33 PM
CO

Photo # 2672 Hay bales need maintenance

Photo # 2694 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2695 Lack of stabilization



Photo # 2696 Lack of stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS SG 431-32 pad

Location ID: 334395



Photo # 2697 Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources