

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579




Photo 1 Genesis #3

Photo 2 Genesis #9-2 PU has no motor, tubing and rod on ground.
PU is considered unused equipment due to not having a motor.

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579



Photo 3 stained soil on Genesis 9-2



Photo 4 flow line appear to be in the open position on Genesis #3

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579



Photo 5 unused equipment sign and 2' hose.

Photo 6 TNK BTRY sign

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579



Photo 7 TNK BTRY



Photo 8 unused equipment 2" hose

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579



Photo 9 Unused equipment/Mechanical issue, pump and motor have no belts and piping has been removed not operational. Stained soil



Photo 10 Stained soil/Mechanical issue piping on ECD

Inspection Photos
Location Name: Genesis #9-2 and #3
Location ID: 319579




Photo 11 sales meter out of calibration.

Photo 12 unused equipment (sign)