

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW.

Location ID: 334947



Photo #9252 From entrance to location.



Photo #9253 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW.

Location ID: 334947



Photo #9254 Secondary containment capacity reduced due to storm water.



Photo #9254 Secondary containment capacity reduced due to storm water.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW.

Location ID: 334947



Photo #9257 Loadline open ended.



Photo #9259 Calibration cards not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW.

Location ID: 334947



Photo #9260 Calibration cards not conspicuously posted.