

# Inspection Photos

3/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location #335781

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 1:** Photos 1-16 taken from throughout the working pad areas of the Location. Photos examples showing BMPs, including vehicle tracking control measures, remain missing or insufficient to stabilize, as well as to minimize erosion, degradation, tracking and sediment transport during wet conditions. Degradation of the working pad has persisted since the 1/25/2023 inspection. Regrading alone will be inadequate to address tracking and stabilization issues. 6 foot measuring stick in photos for reference.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



March 21, 2023

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 5:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 6:** See comments under photo 1.



March 21, 2023

**Photo 7:** See comments under photo 1. Rutting observed to be close to 1 foot in depth at certain areas of the working pad.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 8:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 9:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 10:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 11:** See comments under photo 1.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 12:** See comments under photo 1. Photos 12-16 also show that the eastern working pad areas have not been properly engineered/graded to allow for adequate stormwater discharge, resulting in ponding at production equipment, ponding on the pad, and further destabilization; BMPs to allow for proper discharge, as well as to minimize stormwater contact/ponding at production equipment also required.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 13:** See comments under photo 1 and 12.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 14:** See comments under photo 1 and 12.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



March 21, 2023

**Photo 15:** See comments under photo 1 and 12.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



March 21, 2023

**Photo 16:** See comments under photo 1 and 12.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #335781



**Photo 17:** Photo taken from the methanol tank on the east end of the Location. Photo shows the secondary containment BMP appears to have filled; discolored fluids observed; possible leak at tank; containment no longer appears adequate to contain a spill