

Inspection Photos

API: 071-09060

Operator: WAPITI OPERATING LLC

Inspection Date: 3/22/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09060 | Date: 3/22/2023

Inspection Photos



Photo 1. Facing northwest along the main road near the VPR C 140. Stormwater has caused erosion past the diversion which will continue to erode down the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/22/2023

Inspection Photos



Photo 2. Facing northwest along the main road near the VPR C 140. Stormwater has caused erosion past the diversion which will continue to erode down the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/22/2023

Inspection Photos



Photo 3. The road is rutted and not stabilized at the switch back of the main road traveling to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09060 | Date: 3/22/2023

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-09060 | Date: 3/22/2023