


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location #: 335010



Location Overview: Location is located in a 411 a internal buffer zone.

Section/Township/Range: 36 6S96W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9346 Location lacks stabilization.



Photo #9347 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9345 Location lacks stabilization



Photo #9353 Insufficient tracking BMP.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9368 Insufficient tracking BMP.



Photo #9368 Sediment traps insufficient.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9338 Sediment trap insufficient



Photo #9354 Sediment trap insufficient

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9338 Run on to location is not being controlled.



Photo #9294 Run on to location is not being controlled.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9295 Sediment encroaching on equipment.



Photo #9358 Berms insufficient.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9310 Berms insufficient.



Photo #9312 Ditches insufficient.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9316 Ditches insufficient.



Photo #9300 Ditches insufficient.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9301 Insufficient Stock piled soils BMPs.



Photo #9340 Rip rap BMP insufficient

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9319 Multiple Gully erosion channels.



Photo #9315 Multiple Gully erosion channels.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9322 Multiple Gully erosion channels.



Photo #9334 Multiple Gully erosion channels.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9335 Multiple Gully erosion channels.



Photo #9349 Insufficient velocity BMPs.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE
Location #: 335010



Photo #9351 Insufficient velocity BMPs.