

## Inspection Photos

Location Name: Sack #44-31 Release ID 484022

Location ID: 328359



Photo 1 North end of line replacement operator installed a 3" SDR 11 line inside of a 4' steel line.



Photo 2 South end of line replacement closest to well

## Inspection Photos

Location Name: Sack #44-31 Release ID 484022

Location ID: 328359



Photo 3 Photo of both excavations of line replacement



Photo 4 Photo of both excavations of line replacement



## Inspection Photos

Location Name: Sack #44-31 Release ID 484022

Location ID: 328359



Photo 5 Sack# 44-31



Photo 6 Trash and Debris. (plastic container and tree growing next to motor)



## Inspection Photos

Location Name: Sack #44-31 Release ID 484022

Location ID: 328359



Photo 7 Tree growing next to motor



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources