

TEP
Scott 41C
Location # 427016



Well heads with no access due to water



Separators



TEP
Scott 41C
Location # 427016



Tank battery



Entrance to location



TEP
Scott 41C
Location # 427016



Culvert needs maintained



Culvert needs maintained



TEP
Scott 41C
Location # 427016



Staining



Staining

TEP
Scott 41C
Location # 427016



Debris



Area where ECD was, fencing is still in place and not needed



TEP
Scott 41C
Location # 427016



Lack of stabilization/compaction



Tank labeling



TEP
Scott 41C
Location # 427016



Tank labeling

