

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



Mar 24, 2023 at 10:52:16 AM  
CO



Mar 24, 2023 at 10:52:18 AM  
CO

Photo # 3154 From entrance to location

Photo # 3055 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



Photo # 3156 Location

Photo # 3157 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



Photo # 3158 Location



Photo # 3178 Meter calibration info not conspicuously posted

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



**Photo # 3161 Debris/Wildlife Hazard – Barbed wire laying on the ground**



**Photo # 3162 Debris/Wildlife Hazard – Barbed wire laying on the ground**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



**Photo # 3163 Debris/Wildlife Hazard – Barbed wire laying on the ground**



**Photo # 3165 Rill erosion/sediment encroaching on equipment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



Photo # 2821 Rill erosion



Photo # 3170 Rill erosion

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



**Photo # 3172 Ditch & sediment trap need maintenance**



**Photo # 3173 Berm & Rip Rap need maintenance/transport of sediment off location**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 424-13 Pad

Location ID: 335484



**Photo # 3174 Berm & Rip Rap need maintenance/transport of sediment off location**



**Photo # 3176 Sediment trap/rip rap need maintenance**