

# Inspection Photos

3/24/2023

Operator: CHEVRON USA INC - 16700

Location #314671

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 1:** Photo shows sign at Location entrance in disrepair.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 2:** Photos 2-3 taken from the south end of the Location Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show BMPs to minimize erosion, degradation/tracking and sediment transport are missing or insufficient on the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 3:** See comments under photo 2.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



March 24, 2023



March 24, 2023

**Photo 4:** Well/utility equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 5:** Photo shows partially buried pipe/concrete trash debris.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 6:** Photo taken from the east end of the Location. Photo shows BMPs to manage runoff from the Location are missing or insufficient, resulting in degradation to the off-site slopes east of the Location.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 7:** Photos examples showing soils stockpiles that have been pushed beyond the perimeter of the working pad, therefore expanding the disturbance of the Location. Soils are unconsolidated and are a pollutant source. Photo also shows vegetation covered by soils. BMPs to minimize sediment transport missing.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



March 24, 2023



March 24, 2023

**Photo 8:** See comments under photo 7.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 9:** Photos 9-12 taken from the access road. Photos show BMPs to stabilize, as well as to minimize erosion, degradation/tracking and sediment transport are missing or insufficient at the access road. There are areas of the Access road that does not appear to be properly engineered to adequately manage stormwater.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 10:** See comments under photo 9.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 11:** See comments under photo 9.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location #314671



**Photo 12:** See comments under photo 2. Photo shows tracking/rutting and off-site sediment transport onto Highway 64 from the access road. Refer to inspections #696204791 and #696204758.