

Inspection Photos
Location Name: Facility 1
Spill ID: 484038



Photo 1 – Excavation



Photo 2 – E&P waste stockpiled

Inspection Photos
Location Name: Facility 1
Spill ID: 484038



Photo 3 – No stormwater controls around E&P waste



Photo 4 – Staining

Inspection Photos
Location Name: Facility 1
Spill ID: 484038



Photo 5 – Staining



Photo 6 – Staining