

Interim Reclamation and Stormwater Inspection

Date: 03/23/2023

Operator: P O & G OPERATING LLC - 10634

Location ID: 463256

Inspection Document #: 708200074

Kit Carson County, CO

NWNE Section 14 T11S R46W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 1. Facing northwest at the location. Remnants of a shed was observed in a previous inspection (Doc #700600163) on 09/30/2020, and have not been removed at the time of this inspection. This is now considered trash/debris and needs to be removed.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photos 2 & 3. Facing north at location. Debris and stained soil observed during this inspection. Previous inspection conducted on 09/30/2020 (Doc #700600163) identified this stained soil and required cleanup with a corrective action; it does not appear the operator has performed any cleanup or remedial action to address this, at the time of this inspection.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photos 4 & 5. Close up photos of unknown material that will require disposal. Material had a chemical smell.



Photo 6. Loadout lines without bull plugs or caps.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 7. Facing west at battery. Earthen berm appears inadequate to contain 150% of tank volume with evidence of animal burrows, breached berm walls, and inadequate free board.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 8. Unused equipment being stored on location.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 9. Facing east at battery. Animal burrow within earthen berm, undesirable vegetation (e.g. kochia) and illegible emergency contact/NFPA labels. Sign at left has two different emergency contact numbers.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 10. Loadout lines without bull plug/cap. See comments in Photo 9 for additional.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 11. See comments in Photo 10.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 12. Facing west from battery; undesirable vegetation (e.g. kochia) observed throughout the interim areas.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 13. Facing north from battery; see comments in Photo 12.

Inspection Photos
Location Name: Lowe 2-B
Location ID: 463256



Photo 14. Facing east from access/lease road. It appears the road has been excavated and is not accessible to Staff or emergency services and will need to be repaired.